



NUMBER: 21-006-03 REV. A

GROUP: Transmission

DATE: August 1, 2003

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of DaimlerChrysler Corporation.

THIS BULLETIN SUPERSEDES TECHNICAL SERVICE BULLETIN 21-006-03, DATED JUNE 20, 2003, WHICH SHOULD BE REMOVED FROM YOUR FILES. ALL REVISIONS ARE HIGHLIGHTED WITH **ASTERISKS**** AND INCLUDES ADDITION OF KJ AND 2.4L RS VEHICLES , REVISED NOTES, AND NEW APPLICATION TABLE.**

****THE SOFTWARE IS CURRENTLY AVAILABLE ON TechCONNECT FOR CS, JR, LH, PL, PT, 3.3L AND 3.8L RS/RG, AND TJ VEHICLES**.**

****THIS BULLETIN IS BEING PROVIDED IN ADVANCE FOR 2.4L RS/RG VEHICLES. THE SOFTWARE WILL BE AVAILABLE ON TechCONNECT ON OR AFTER AUGUST 18, 2003. KJ SOFTWARE WILL BE AVAILABLE ON TechCONNECT ON OR AFTER SEPTEMBER 3, 2003.****

SUBJECT:

Transmission Harsh 4-3 Downshift

OVERVIEW:

This bulletin involves reprogramming the Transmission Control Module (TCM).

MODELS:

2004	(CS)	Pacifica
2003 - 2004	(JR)	Sebring Convertible/Sebring Sedan/Stratus Sedan
**2003	(KJ)	Liberty **
**2003	(KJ)	Cherokee (International Markets) **
2003 - 2004	(LH)	300M/Concorde/Intrepid
2003	(PL)	Neon/SX 2.0
2003	(PT)	PT Cruiser
2003	(RG)	Chrysler Voyager (International Markets)
2003	(RS)	Town & Country/Caravan/Voyager
2003	(TJ)	Wrangler

NOTE: **Refer to the following table for specific applications.**

Model	Engine	Transmission	Built On Or Before
CS	3.5L	41TE	July 10, 2003
JR	2.4L or 2.7L	41TE	July 2, 2003

061454

DaimlerChrysler Corporation
Dealer Technical Operations

Model	Engine	Transmission	Built On Or Before
KJ	3.7L	42RLE	
LH	2.7L or 3.5L	42LE	
PL	2.0L	41TE	
PT	2.0L or 2.4L	41TE	
RS/RG	2.4L, 3.3L or 3.8L	41TE	
TJ	4.0L	42RLE	

SYMPTOM/CONDITION:

Vehicle may exhibit, after an extended soak (several hours), a harsh 4-3 downshift.

DIAGNOSIS:

Using a Scan Tool (DRBIII®) with the appropriate Diagnostic Procedures, verify all engine systems are functioning as designed. If DTCs are present record them on the repair order and repair as necessary before proceeding further with this bulletin.

If the vehicle operator describes the Symptom/Condition, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
AR (1)	04669020	Label, Authorized Software Update
AR (1)	04275086AB	Label, Authorized Modification

EQUIPMENT REQUIRED:

NPN	Battery Charger
CH2002	General Purpose Interface Bus Cable Assembly
CH6000A	Scan Tool (DRBIII®)
CH7000A/7001A	J1962 Cable
	TechCONNECT Workstation

NOTE: **An updated J1962 cable has been released. This cable has a red colored connector at the DRBIII® connection. Use this cable whenever a flash is being performed.**

REPAIR PROCEDURE:

1. Check the transmission fluid level. If fluid level is full proceed to step 2. If fluid level is low, diagnose and repair fluid leak. Proceed to step 2.

NOTE: Whenever a PCM/TCM is replaced or reprogrammed, the software in the controller and DRBIII® must be verified as having the latest revision level. If a controller software update flash is available, complete the flash and labeling requirement as directed in the appropriate service bulletin identified on the TechCONNECT.


2. Connect a battery charger and set as close to 14 volts charge as possible.
3. Flash the controller using the TechCONNECT and DRBIII®.

NOTE: **Using the DRBIII® preform the proper Quick Learn procedure. Refer to the service information available in TechCONNECT or the appropriate service manual in Section 8E - Electronic Control Modules.**

NOTE: Due to the PCM reprogramming procedure, a DTC may be set in other modules (TCM, BCM, MIC, SKIM, etc.) within the vehicle, if so equipped. Some DTC's may cause the MIL to illuminate. All DTC's relate to a loss of communications with the module that is being reprogrammed. Check all modules, record the DTC's, and erase these DTC's prior to returning the vehicle to the customer. Erase any DTC's in the PCM only after all other modules have had their DTC's erased.

NOTE: The following steps are required by law.

4. Type the necessary information on the "Authorized Software Update Label" p/n 04669020 (Fig. 1). Attach the label to the controller and cover the label with the clear plastic overlay.



80bb0a94

Fig. 1 AUTHORIZED SOFTWARE UPDATE LABEL

5. Type the necessary information on the "Authorized Modification Label" p/n 04275086AB and attach near the VECI label (Fig. 2).

DaimlerChrysler	AUTHORIZED MODIFICATIONS	IF THE MODIFICATIONS HAVE BEEN APPROVED AS APPROPRIATE, BY EPA AND CHS.
THE FOLLOWING MODIFICATIONS HAVE BEEN MADE:		
<div style="border: 1px solid black; width: 100px; height: 40px; margin: 0 auto; display: flex; align-items: center; justify-content: center;"> 1 </div>		
CHANGE AUTHORITY	DEALER CODE	DATE
<div style="border: 1px solid black; width: 100px; height: 20px; margin: 0 auto; display: flex; align-items: center; justify-content: center;"> 2 </div>	<div style="border: 1px solid black; width: 100px; height: 20px; margin: 0 auto; display: flex; align-items: center; justify-content: center;"> 3 </div>	<div style="border: 1px solid black; width: 100px; height: 20px; margin: 0 auto; display: flex; align-items: center; justify-content: center;"> 4 </div>
<small>6276086A3</small>		

80734528

Fig. 2 AUTHORIZED MODIFICATION LABEL

- 1 - POWERTRAIN CONTROL MODULE P/N (INSERT P/N) USED
- 2 - CHANGE AUTHORITY: TSB XX-XXX-XX
- 3 - DEALER CODE: XXXXX
- 4 - DATE: XX-XX-XX

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
08-19-37-90	Reprogram Transmission Control Module	0.5 Hrs.

FAILURE CODE:

FM	Flash Module
----	--------------