

ARTICLE BEGINNING

MANUFACTURER'S SUGGESTED SCHEDULED MAINTENANCE

The manufacturer recommends the belt be replaced every 105,000 miles.

REMOVAL & INSTALLATION

Tips

Click a link to view tip



Eric O. Tip: Timing Belt - R&R



Tech1 Tip: interference engine - '01 2.5L

TIMING BELT

Tips

Click a link to view tip



Tech1 Tip: INTERFERENCE MOTOR


Removal

1. Disconnect negative battery cable. Raise and support vehicle. Remove engine under cover.
2. Lower vehicle. Remove radiator coolant reservoir, and set aside. Remove electric cooling fan and radiator shroud.
3. On Impreza and Forester, remove accessory drive belt cover. On all models, remove accessory drive belts.
4. Hold crankshaft pulley stationary, and remove crankshaft pulley center bolt. Remove crankshaft pulley. Remove timing belt covers.
5. Turn crankshaft to align crankshaft and camshaft timing notches with marks on rear timing cover and engine block. See [Fig. 1](#) and [Fig. 2](#). On manual transmission models, remove timing belt guide from top of crankshaft pulley.
6. On all models, if reusing old belt, use White paint to mark timing belt in relation to sprocket timing marks. See [Fig. 3](#). Also mark timing belt direction of travel. On 2000 and newer vehicles, count number of teeth between marks. For correct count, see [INSTALLATION MARK MEASUREMENT SPECIFICATIONS](#) table.
7. Remove No. 2 timing belt idler pulley. See [Fig. 4](#). Remove timing belt. Remove timing belt automatic tensioner with rod facing up.

INSTALLATION MARK MEASUREMENT SPECIFICATIONS

Application ⁽¹⁾	Number Of Teeth
Baja	

2003-05	
Z-1	46.8
Z-2	43.7
Forester, Legacy & Outback	
2000-01	
Z-1	44.0
Z-2	40.5
2002-05	
Z-1	46.8
Z-2	43.7
Impreza	
2000-02	
Z-1	44.0
Z-2	40.5
2003-05	
Z-1	46.8
Z-2	43.7
(1) To determine distances Z-1 and Z-2, see Fig. 3 .	



[Fig. 1: Identifying Timing Belt Routing & Timing Marks](#)
 Courtesy of SUBARU OF AMERICA, INC.






Fig. 2: Aligning Camshaft & Crankshaft Timing Marks
Courtesy of SUBARU OF AMERICA, INC.





Fig. 3: Marking Timing Belt For Reinstallation
Courtesy of SUBARU OF AMERICA, INC.



G00019670

Fig. 4: Removing No. 2 Timing Belt Idler Pulley

Courtesy of SUBARU OF AMERICA, INC.

Inspection **Tips**

Click a link to view tip



Tech1 Tip: Bent valves !

1. Inspect timing belt for wear on rounded edges of drive teeth. Inspect belt for signs of oil contamination. Replace belt if it is damaged or contaminated.
2. Inspect belt automatic tensioner oil seals for leaks. Slight trace of oil at rod oil seal does not indicate a problem. Inspect rod ends for abnormal wear and scratches.
3. Measure extension of rod beyond tensioner body. Holding tensioner with rod facing up, rod extension should be .204-.244" (5.2-6.2 mm). See [Fig. 5](#). Replace automatic tensioner if rod extension is not as specified.

CAUTION: Always use a vertical type pressing tool to compress automatic tensioner rod. DO NOT use a bench vise to compress rod. It may take more than 3 minutes to compress

the automatic tensioner rod.

4. Place automatic tensioner in a press with tensioner rod facing up. Apply 66 lbs. (294 N) of pressure on rod. If rod moves down easily, replace automatic tensioner.
5. Inspect automatic tensioner and idler pulleys for worn bearings or lubricant leaks. Replace as necessary.




Fig. 5: Checking Automatic Tensioner Rod Extension
Courtesy of SUBARU OF AMERICA, INC.


Installation 

CAUTION: To prevent damage, DO NOT apply more than 2205 lbs. (9807 N) of pressure to automatic adjuster rod. Do NOT press automatic tensioner rod past the top surface of the housing.

1. Ensure crankshaft and camshaft timing marks are still aligned. Place automatic adjuster in a press with rod facing up. Apply 66 lbs. (294 N) pressure to end of rod. **SLOWLY** compress rod (taking more than 3 minutes) into housing until rod and housing holes are aligned. Insert locking pin through holes. See [Fig. 6](#).
2. Install automatic tensioner on engine with locking pin in place. Install idler pulleys (if removed).
3. Ensure crankshaft and camshaft timing marks are still aligned. Install timing belt. If reusing old belt, ensure belt direction of rotation is correct and mating marks are aligned. Count number of teeth between crankshaft sprocket and camshaft sprockets so that belt will be installed in same position. For correct count of teeth, see [INSTALLATION MARK MEASUREMENT SPECIFICATIONS](#) table. To determine distances Z-1 and Z-2, see [Fig. 3](#).
4. Install No. 2 idler pulley on engine. Remove automatic tensioner locking pin. On manual transmission models, install timing belt guide over crankshaft pulley. Adjust clearance between belt guide and belt to .020-.058" (.5-1.5 mm). See [Fig. 7](#).


CAUTION: If tightening angle of crankshaft pulley bolt is less than 65 degrees, bolt is damaged. Bolt must be replaced.

5. On all models, install timing belt covers. Clean crankshaft pulley bolt and bolt hole. Install crankshaft pulley. Coat crankshaft pulley bolt threads with engine oil. Install bolt. While holding crankshaft pulley stationary, tighten bolt to specification. See [TORQUE SPECIFICATIONS](#).
6. Install accessory drive belts. Install radiator fan assembly. To complete installation, reverse removal procedures. Adjust drive belts to proper tension.



[Fig. 6: Installing Automatic Tensioner Pin](#)

Courtesy of SUBARU OF AMERICA, INC.



G00019668

Fig. 7: Checking Timing Belt Guide Clearance

Courtesy of SUBARU OF AMERICA, INC.

TORQUE SPECIFICATIONS

TORQUE SPECIFICATIONS

Application	Ft. Lbs. (N.m)
Camshaft Sprocket Bolt	58 (78)
Crankshaft Pulley Bolt	
Step 1	33 (44)
Step 2 ⁽¹⁾	
2.2L	94 (127)
2.5L	133 (180)
Idler Pulley Bolt	29 (39)
Timing Belt Automatic Tensioner Bolt	29 (39)
	INCH Lbs. (N.m)
Timing Belt Cover Bolt	44 (5)

Timing Belt Guide Bolt (M/T)	89 (10)
Valve Cover Bolt	44 (5)
Water Pump Bolt	89-124 (10-14)
(1) Ensure tightening angle is between 65-75 degrees. If tightening angle is less than specified, bolt is damaged and must be replaced.	

© 2008 Mitchell Repair Information Co., LLC.