

FORD:
2008-2009 Taurus X, Taurus

MERCURY:
2008-2009 Sable

LINCOLN:
2009 MKS

This article supersedes TSB **07-26-8** to update the model years, vehicle lines and add a production fix date.

ISSUE

Some 2008-2009 Taurus, Taurus X, Sable and 2009 MKS vehicles built on or before 6/23/2009 may exhibit a clicking, popping, rubbing, grunting, squeaking, or creaking noise coming from the wheel well area. The noise may be heard at the top of the strut rod. Typically, the noise is heard in the front outboard wheel while turning. This noise may be caused by the jounce bumper rubbing against the strut rod, or the dust boot rubbing against the strut mount cup.

ACTION

Follow the Service Procedure steps to correct the condition.

SERVICE PROCEDURE

1. Raise the vehicle as described in Workshop Manual, Section 100-02.
2. Reach through the spring and pull the strut dust cover and jounce bumper assembly straight down, out of the strut bearing mount.
3. Apply Motorcraft Silicone Brake Caliper Grease and Dielectric Compound: (Figure 1)
 - To the entire length of the chromed strut rod above the jounce bumper and 360° around the rod.
 - To the top and sides of the uppermost part of the dust boot.




Figure 1 - Article 09-19-4

4. Slide the dust cover and jounce bumper assembly upward into its original location on the strut.
5. Repeat the procedure on the other side of the vehicle.
6. Lower the vehicle.

PART NUMBER	PART NAME
XG-3-A	Motorcraft® Silicone Brake Caliper Grease and Dielectric Compound

WARRANTY STATUS: Eligible Under Provisions Of New Vehicle Limited Warranty Coverage
IMPORTANT: Warranty coverage limits/policies are not altered by a TSB. Warranty coverage limits are determined by the identified causal part.

NOTE: The information in Technical Service Bulletins is intended for use by trained, professional technicians with the knowledge, tools, and equipment to do the job properly and safely. It informs these technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by "do-it-yourselfers". Do not assume that a condition described affects your car or truck. Contact a Ford, Lincoln, or Mercury dealership to determine whether the Bulletin applies to your vehicle. Warranty Policy and Extended Service Plan documentation determine Warranty and/or Extended Service Plan coverage unless stated otherwise in the TSB article. The information in this Technical Service Bulletin (TSB) was current at the time of printing. Ford Motor Company reserves the right to supersede this information with updates. The most recent information is available through Ford Motor Company's on-line technical resources.

TSB 09-19-4 (Continued)

OPERATION	DESCRIPTION	TIME
091904A	2008-2009 Taurus/Taurus X/Sable/2009 MKS: Apply Grease To The Dust Boot And Strut Rod Following Service Procedure (Do Not Use With Any Other Labor Operations)	0.3 Hr.

DEALER CODING	CONDITION
BASIC PART NO. 18124	CODE 14