

#00-00-89-016: Information - June, 2000 Bulletin Summary - (Jul 6, 2000)

Subject: Information -- June, 2000 Bulletin Summary

Models: 2001 and Prior Passenger Cars and Trucks



The following list is a summary of all the bulletins that were issued in June, 2000. It is intended to let dealerships quickly review the most current bulletins in order to better service their customers. Dealerships will be receiving this type of summary, published as a bulletin, every month.

Bulletin Title	Vehicles Affected	Bulletin Number
<i>Engine</i>		
Idle Stumble, Low Oil Pressure Cold Concerns, DTCs P0101, P1441 (Reprogram PCM with Calibration Enhancement)	2000 Oldsmobile Intrigue; 2001 Oldsmobile Aurora with 3.5L Engine	00-06-04-022
Proper Service of Quick Connect EVAP System Connectors	1985-2001 Passenger Cars and Trucks	00-06-04-021
Battery Testing and Replacement	1997-2001 Passenger Cars and Trucks (except 2001 Chevrolet Corvette)	00-06-03-003
No Start, Discharged Battery (Contact OnStar® to have "Theft Notification" Feature Turned Off)	1999-2000 Cadillac Escalade; 1999-2000 GMC Denali	00-06-03-005
Increased Accelerator Pedal Effort (Replace Throttle Body)	1999-2000 Chevrolet and GMC C/K Pickup Models (Silverado and Sierra) with 4.8L, 5.3L or 6.0L V8 Engine	00-06-04-007A
Service Engine Soon Lamp Illuminated/DTCs P0230, P0748, P1689 Stored in Memory (Install Harness Assembly Service Kit)	2000 Buick LeSabre; 2000 Pontiac Bonneville	00-06-04-023
Engine Misfire, Water in Fuel, Service Engine Soon Lamp Illuminates, DTC P0300 Set (Replace EVAP Canister Vent Hose Asm/Replace EVAP Canister If Necessary)	1999-2000 Chevrolet and GMC C/K Pickup Trucks (Silverado and Sierra)	00-06-04-024
Possible Oil Filter Damage or Oil Leak from Oil Filter Area (Install Oil Filter Adapter)	1999-2000 Chevrolet and GMC K Pickup Models with 7.4L Engine	00-06-01-014
Discolored Coolant in Cooling System and Contamination of the Coolant Recovery Reservoir (Clean the Coolant Recovery Reservoir and Test the Radiator Cap)	2000 Buick LeSabre; 2000 Pontiac Bonneville With 3.8L Engine	00-06-02-005
California Consent Order on Settlement of Lawsuit on Batteries (Proposition 65)	2001 and Prior Passenger Cars and Trucks	00-06-03-006
Reduced Engine Power, DTC(s) P1125, P1275, P1276, P1280, P1281, P1285 and/or P1286 May Be Present (Current or	1999 Chevrolet and GMC B7 Bus, C6-7 Conventional, P32 Medium Duty Models	99-06-04-039A

in History) (Replace Accelerator Pedal Assembly)	With 7.4L Engine	
<i>Transmissions</i>		
ACDelco® Remanufactured Transmissions	1996 and Prior Passenger Cars and Trucks	00-07-30-011
Automatic Transmission Shift Lever Handle Difficult to Operate (Install Different Design Handle)	1999-2000 Oldsmobile Alero; 1999-2000 Pontiac Grand Am	00-07-30-012
ABS Light On at High Speeds (Above 70 mph or 113 km/h), Code C0237 Set (Install New PCM)	2000 Chevrolet and GMC S/T Pickup Models; 2000 Isuzu Hombre With 2.2L Engine and 4L60-E Automatic Transmission	00-06-04-025
<i>Steering, Suspension , Tires and Wheels</i>		
Steering or Front End Road Induced Vibration	1999-2000 Chevrolet and GMC C1500 Pickups (Silverado and Sierra)	00-02-35-004
Clunking Noise Under the Hood and Can Be Felt in the Steering Wheel (Replace the Upper Intermediate Steering Shaft Assembly)	1999-2000 Chevrolet and GMC C2/K1/K2 Pickup Models (Silverado and Sierra); 2000 Chevrolet and GMC C/K Utility Models (Suburban, Tahoe, Yukon, Yukon XL) With Recirculating Ball-Type Steering	00-02-35-003
<i>Body and Accessories</i>		
Daytime Running Lamps (DRL) Disable Procedure	2000 Chevrolet and GMC C/K Pickup (Silverado and Sierra), M/L, S/T Models; 2000 Oldsmobile Bravada; 2000 Isuzu Hombre	99-08-42-007A
Noise at Torsion Bar Location, Cab Difficult to Open, Torsion Bar Broken (Inspect/Replace Cab Pivot Torsion Bar)	1997-1998 Chevrolet and GMC F Model T-Series Medium Duty Tilt Cab Trucks	00-08-63-003
Intermittent Digital Instrument Cluster Concerns (Reprogram Instrument Panel Cluster (IPC))	2000 Cadillac DeVille	00-08-49-005
Floor Console Cupholder Too small (Replace Console and Console Shift Lever Trim Plate)	1999-2000 Oldsmobile Alero	00-08-49-004
Left Headlamp Door Does Not Stay Closed (Shim Headlamp Door Motor/Actuator and Replace Insulators)	2000 Chevrolet Corvette	00-08-42-002
Rattle/Squeak in Right Side of Instrument Panel or Right Front Door Trim Panel Scratched or Right Side End of Instrument Panel Contacting Door Trim Panel (Remove Instrument Panel Assembly and Align Tie Bar)	1995-2000 Chevrolet Cavalier; 1995-2000 Pontiac Sunfire	00-08-49-003
Generator Whine in Audio System (Install	2000 Chevrolet and GMC C/K 1500/2500 Series Utility Trucks	

New Ground for Radio and Amplifier and/or Replace Radio)	(Suburban, Tahoe, Yukon/XL) With Uplevel Trim and Audio Package	00-08-44-005
Headlamp Capsule Availability	1997-2000 Chevrolet Venture; 1997-2000 Oldsmobile Silhouette; 1997-2000 Pontiac Trans Sport	00-08-42-003
<i>General Information</i>		
June, 2000 Labor Time Guide Updates	1996-2001 Passenger Cars and Trucks	00-00-89-012
May, 2000 Bulletin Summary	2001 and Prior Passenger Cars and Trucks	00-00-89-013
<i>Restrictions</i>		
Disabling SIR System Prior to Service Procedure for Front Doors	1998-1999 Cadillac DeVille	00-09-41-003

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.