



NUMBER: 05-006-08

GROUP: Brakes

DATE: December 9, 2008

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of Chrysler LLC.

SUBJECT:

Brake Front Pad Lining Life and Noise

OVERVIEW:

This bulletin involves installing new brake linings and replacing both brake rotors as required.

MODELS:

2008 (RT) Town & Country/Grand Caravan

NOTE: This bulletin applies to vehicles equipped with Anti-Lock 4-Wheel-Disc Brakes and Non Adjustable Pedals (sales codes BRG & XA8)

SYMPTOM/CONDITION:

Front brake pads may exhibit excessive noise, squeal/shudder/vibration and/or lining life complaints.

DIAGNOSIS:

If the above condition is present, perform the repair procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68053152AA	Front Brake Pad Kit
2	04721995AA	Front Brake Rotor

REPAIR PROCEDURE:

1. Using the procedures outlined in TechCONNECT: Service Information tab /05 - Brakes, Base/Hydraulic Mechanical/PADS, Brake, Front/ Removal - remove the front pads.
2. Using the procedures outlined in TechCONNECT: Service Information tab /05 - Brakes, Base/Hydraulic Mechanical/ROTAR, Brake, Front/ Removal - remove and replace the front brake rotors (p/n 04721995aa).

NOTE: Rotor replacement is recommended when switching to this type brake pad. Standard brake service procedures apply thereafter.

3. Install new pads (p/n 68053152aa).

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Amount
05-21-10-97	Install New Front Pads, Replace Both Front Rotors	0.6 Hrs.

FAILURE CODE:

ZZ	Service Action
----	----------------

