


1999 Acura CL V6-3.0L SOHC (VTEC)[Vehicle Level](#) → [Heating and Air Conditioning](#) → [Blower Motor](#) → [Service and Repair](#) → [Overhaul](#) ↕**Overhaul**[Notes](#)

Zoom

Sized for Print

NOTE:

- The recirculation control motor, the power transistor, the blower motor high relay and the blower motor can be replaced without removing the blower

unit.

- Before reassembly, make sure that the recirculation control doors and linkage move smoothly without binding.
- After reassembly, make sure the recirculation control motor runs smoothly.
- Make sure that there is no air leakage.

© 2010 ALldata LLC. All rights reserved.

[Terms of Use](#)