

2006 Audi A3 L4-2.0L Turbo (BPY)

| |
|---|
| Vehicle Level → Technical Service Bulletins → All Technical Service Bulletins ← |
|---|

All Technical Service Bulletins

Information

| <u>Number</u> | <u>▼ Date</u> | <u>Title</u> |
|-------------------------|----------------------------|--|
| 300803 | 12/22/2008 | M/T - Clutch Does Not Engage Smoothly |
| 240885 | 12/22/2008 | Air Induction - MIL ON/DTC's P0171/P2187 |
| 170833 | 12/22/2008 | Engine - Oil Filter Cartridge Replacement Precautions |
| 010836 | 12/22/2008 | Engine Controls - MIL ON/DTC's P1847/P1624 |
| 210805 | 12/22/2008 | Engine -Turbocharger Recirculation Valve/DTC P0299 Set |
| 000822 | 12/18/2008 | Fuel System - Driveability Associated With Fuel Quality |
| 170832 | 12/17/2008 | Engine - MIL ON/DTC's P1297/P2187/P2279 |
| 9108180 | 12/17/2008 | Navigation System - Navigation Plus, Various Complaints |
| 9108181 | 12/17/2008 | Navigation System - Reduced Functionality/Error Message |
| 460815 | 12/16/2008 | Brakes - Squealing Noise |
| 370819 | 12/16/2008 | A/T Controls - Hard Jerking In Reverse At Idle |
| 350804 | 12/16/2008 | M/T - Hard To Downshift to 5th Gear/Can't Slect 5th Gear |
| 010833 | 12/15/2008 | Computers/Controls - Software Version Management |
| 9108178 | 12/15/2008 | Audio System - CD Playback Problem Information |
| 240882 | 12/10/2008 | Engine Controls - MIL ON/DTC P0601 Stored in ECM |
| 9108160 | 12/10/2008 | Electrical - Steering Wheel Multifunction Switches Inop. |
| 9108159 | 12/10/2008 | Audio System - Satellite Radio Antenna Service Caution |
| 010827 | 12/09/2008 | Electrical - Windows/Locks/Sunroof Inop. One Time |
| 570821 | 12/09/2008 | Keyless Entry - Remote Control Key Inoperative |
| 570822 | 12/09/2008 | Keyless Entry - Remote Transmitter Memory Limitations |
| 900818 | 12/08/2008 | A/C - Insufficient/Poor Cooling Ability |
| 900819 | 12/08/2008 | Instruments - Clock Resets After Vehicle Sits A While |

| | | |
|-------------------------|----------------------------|--|
| 870805 | 12/05/2008 | A/C - Unpleasant Musty Odors |
| 870813 | 12/05/2008 | A/C - Refrigerant System Cleaning |
| 870807 | 12/05/2008 | A/C - Does Not Cool |
| 870808 | 12/05/2008 | A/C - Poor Performance/Not Cooling |
| 870804 | 12/05/2008 | A/C - Clicking/Ticking Noises From The Dash |
| 660821 | 12/05/2008 | Windshield Wipers - Front Wipers Inoperative |
| 640815 | 12/05/2008 | Wipers/Washers - Windshield Wipers Streak/Smear/Noisy |
| 700839 | 12/04/2008 | Interior - Leather Upholstery Cleaning Tips |
| 700838 | 12/04/2008 | Interior - Cleaning Tips For Fabrics, Vinyls, Plastics |
| 690804 | 12/03/2008 | Airbag - Replacement Interval Change |
| 690810 | 12/03/2008 | Restraints - Interior Cleaning Solvent Precautions |
| 690805 | 12/03/2008 | Restraints - Airbag/Safety Belt Deployment, Inquiries |
| 9108149 | 12/03/2008 | Navigation System - DVD Read Error/System Freezes |
| 440816 | 12/03/2008 | Tire Monitor System - System Overview |
| 640810 | 12/02/2008 | Interior - Master Window Switch Jams/Inoperative |
| 680810 | 12/02/2008 | Interior - Won't Open/Glove Compartment Opens Slowly |
| 570817 | 12/02/2008 | Body - Window One Touch Feature is Inoperative |
| 970825 | 12/01/2008 | Engine Controls - MIL ON/DTC P1545/0121/0221/0222 |
| 600820 | 12/01/2008 | Body - Rattling Noise From The Sunroof Area |
| 600817 | 12/01/2008 | Sunroof - Sunroof Blind Sticks or Does Not Retract |
| 600816 | 12/01/2008 | Body - Squeaking/Grinding Noise From B-Pillar/Sunroof |
| 600809 | 11/26/2008 | Sunroof - Buffeting Noise in Cabin When Open |
| 600808 | 11/26/2008 | Sunroof - Wind and/or Buzzing Noise in Sliding Roof |
| 600810 | 11/26/2008 | Body - Sunroof Sunshade Won't Latch Closed |
| 570816 | 11/26/2008 | Body - Noise From The Lower Door Hinges |
| 010816 | 11/25/2008 | Engine Controls - Hesitation on Acceleration |

| | | |
|------------------------|----------------------------|---|
| 340805 | 11/25/2008 | A/T - No Vehicle Acceleration When Selecting 'D, R, S' |
| 340804 | 11/25/2008 | M/T - Clacking Noise On Load Change |
| 170826 | 11/21/2008 | Engine - Oil Consumption Measurement |
| 190816 | 11/21/2008 | Cooling System - Coolant Leak From The Radiator |
| 200807 | 11/21/2008 | Fuel System - Rattling Noises From Passenger Floor Area |
| 170824 | 11/21/2008 | Engine - Oil Quality Standard VW 502 00 |
| 170827 | 11/21/2008 | Engine - Oils Meeting VW Standards VW 502 00/505 01 |
| 190818 | 11/21/2008 | Cooling System - Coolant Reservoir Appear To Be Leaking |
| 010809 | 11/19/2008 | Engine - Runs Rough/MIL ON/Misfire DTC's Set |
| 240859 | 11/19/2008 | Engine - MIL ON/Misfire DTC's Stored in Memory |
| 440814 | 11/19/2008 | Wheels - Wheel Bolt Torque Precautions |
| 010807 | 11/19/2008 | Engine Controls - Engine Intermittently Won't crank |
| 240858 | 11/19/2008 | Fuel System - MIL ON/Fuel Pressure DTC's Set |
| 260813 | 11/18/2008 | Engine Controls - MIL ON / DEC P0420 In ECM |
| 940848 | 11/18/2008 | Lights - Condensation Visible Inside Exterior Lamps |
| 940845 | 11/17/2008 | Lighting - Interior Switch Illumination Always ON |
| 970815 | 11/17/2008 | Computers/Controls Various Codes In Different Modules |
| 010805 | 11/17/2008 | Electrical - Multiple Malfunctions After Window Tinting |
| 200805 | 11/14/2008 | Fuel System - Fuel Neutralization Procedure |
| 940840 | 11/14/2008 | Lighting - Headlamp Aiming Information |
| 960814 | 11/14/2008 | Lighting - Luggage Compartment Light Inoperative |
| 940835 | 11/13/2008 | Lighting - Headlamps Turn ON/OFF Without Reason |
| 940832 | 11/13/2008 | Lighting - Dynamic Headlight Control Defective Lamp ON |
| 940831 | 11/13/2008 | Lighting - Bulb Out lamp ON/Codes 02745/02746 Set |
| 940830 | 11/13/2008 | Lighting - Headlamp Low Beam Inoperative |
| 940822 | 11/13/2008 | Lighting - Light Bulb Warning For Backup Bulb |

| | | |
|-------------------------|----------------------------|--|
| 940824 | 11/13/2008 | Lighting - Headlamp Range Control Warning/DTC 01771 |
| 960812 | 11/13/2008 | Lighting - Daytime Running Lamps Are Inoperative |
| 960810 | 11/11/2008 | Garage Door Opener - Cannot Adjust To HomeLink Sys |
| 9108122 | 11/11/2008 | Audio/Interior - Speaker Hum/Buzz/Crackle/Rattle |
| 910886 | 11/10/2008 | Cell Phone - Bluetooth(R) Inop Using Navigation Controls |
| 910884 | 11/10/2008 | Audio System - DTC 00858 Information |
| 910885 | 11/10/2008 | Audio System - Station Buttons Loose Or Damaged |
| 910891 | 11/10/2008 | Radio - Only One Satellite Station Displays |
| 910864 | 11/07/2008 | Navigation System - Route Guidance Self Activation |
| 910881 | 11/07/2008 | Navigation System - Route Guidance Inaccurate |
| 910861 | 11/07/2008 | Cell Phone - LG VX8700 Drops Bluetooth(R) Connection |
| 910863 | 11/07/2008 | Audio System - Speakers Hiss With Radio Off |
| 910872 | 11/07/2008 | Audio System - Radio DTC 00858 Information |
| 900813 | 11/06/2008 | Instruments - Service Interval Programming Information |
| 910857 | 11/06/2008 | Audio System - Radio Antitheft Code Information |
| 970811 | 11/06/2008 | Audio System - No Sound From iPod(R)/CD Changer |
| 460813 | 11/05/2008 | Brakes - Pulsation Diagnostic Information |
| 900810 | 11/05/2008 | Instruments - Fuel Gauge Reads Empty With Fuel In Tank |
| 910855 | 11/05/2008 | Audio System - Radio Knobs Broken/Pressed In |
| 900809 | 11/05/2008 | Instruments - Low Oil Light On After Oil Is Refilled |
| 470804 | 11/04/2008 | Brakes - Moan On Acceleration Or Turns |
| 450802 | 11/04/2008 | ABS/TCS - ESP Lamp ON/DTC Stored In ECM Information |
| 400809 | 10/30/2008 | Suspension - Shock Absorber Leak Assessment |
| 190807 | 10/27/2008 | Cooling System - Coolant Leak From The Coolant Flange |
| 240841 | 09/25/2008 | Campaign - Fuel Pressure Sensor Replacement |
| 910842 | 09/15/2008 | Audio System - Buzz/Hum/Hiss From Speakers |

| | | |
|--------------------------------|----------------------------|---|
| 910840 | 09/11/2008 | Parking Assist System - Warnings With No Obstacles |
| 970805 | 09/04/2008 | Engine Controls - MIL ON/Throttle Valve DTC's In ECM |
| 100802 | 08/05/2008 | Engine - Inspect for Debris When Replacing Engine |
| 910821 | 06/04/2008 | Cell Phone - Bluetooth(R) Bonding Tone Volume Level |
| 150805 | 06/02/2008 | Engine - MIL ON/DTC's P2293/P0087/P1093 Set |
| 240813 | 03/11/2008 | Campaign - ECM Update for MIL ON/Intake DTC's |
| 240810 | 03/03/2008 | Engine Controls - MIL ON/Intake Manifold DTC's Stored |
| 570802 | 02/28/2008 | Keyless Entry - Remote Control Inoperative |
| 240719 | 11/19/2007 | Fuel System - MIL ON/DTC's DTC P310B/P129F Set |
| 010718 | 08/29/2007 | Campaign - Engine Control Module Software Update |
| 170707 | 08/07/2007 | Engine - Oil Filler Cap Leaks/Blue Exhaust Smoke |
| 150702 | 06/18/2007 | Fuel System - MIL ON/DTC P2293/P0087/P1093 |
| 240707 | 06/11/2007 | Engine Controls - MIL ON DTC P0130/3255/3266 |
| 210702 | 06/04/2007 | Engine - MIL ON/DTC 0299 Set |
| 190705 | 05/16/2007 | Campaign - Replacement of Coolant Flange O-Ring |
| 640703 | 04/13/2007 | Body - Driver Window Switch Sticking/Windows Inop. |
| 600706 | 04/05/2007 | Campaign - Sunshade Latch is Inoperative |
| 690703 | 03/09/2007 | Campaign - Air Bag Module Reprogramming |
| 010704 | 02/26/2007 | Campaign - ECM Software Update for MIL ON/DTC P0601 |
| 350701 | 01/31/2007 | A/T - Momentary Delay When Accelerating (DSG Gearbox) |
| 910635 | 12/12/2006 | Audio System - Radio Inoperative in Satellite Mode |
| 000607 | 10/30/2006 | Engine Controls - MIL ON/Multiple DTC's Set in ECM |
| 910621 | 10/18/2006 | Audio System - Satellite Antenna Module Precautions |
| 170602 | 08/02/2006 | Engine - Oil Leak From Oil Filter Housing |
| NHTSA06V293000 | 07/31/2006 | Recall 06V293000: Side Curtain Air Bag Replacement |

| | | |
|------------------------|----------------------------|--|
| 910612 | 06/01/2006 | Audio System - No Satellite Audio/No Preview Menu |
| 910614 | 06/01/2006 | Audio System - Tuner Interferes With Tire Monitor System |
| 910610 | 05/23/2006 | Audio System - No Sound in Satellite Mode |
| 340602 | 03/15/2006 | A/T - No Movement After Selecting 'D', 'R' or 'S' |
| 010603 | 01/26/2006 | Fuel - Driveability Issues Due To Low Quality Fuel |
| 600602 | 01/24/2006 | Body - Sunroof Sun Shade Binds/Won't Retract |
| 910506 | 04/29/2005 | Audio System - Poor Satellite Radio Reception |
| 940504 | 04/25/2005 | Lighting - Exterior Lighting Moisture Accumulation |