

2002 Suzuki Truck XL-7 Standard 4WD V6-2.7L

[Vehicle Level](#) → [Body and Frame](#) → [Bumper](#) → [Front Bumper](#) → [Service and Repair](#) ←

Service and Repair

[Notes](#)

Front [Bumper](#) Components

NOTE:

- Fasteners are important attaching parts in that they could affect the performance of vital components and systems, and/or could result in major repair expense. They must be replaced with one of the same part number or with an equivalent part if replacement becomes necessary. Do not use a replacement part of lesser quality or substitute design. Torque values must be used as specified during reassembly to assure proper retention of these parts.
- Before removing front [bumper](#), remove [fender](#) lining and disconnect connector of side marker.

