


2000 Mitsubishi Truck Montero Sport LTD 4WD V6-3.5L SOHC

[Vehicle Level](#) → [Heating and Air Conditioning](#) → [Evaporator Core](#) → [Service and Repair](#) → [Removal and Installation](#) ←

Removal and Installation

[Notes](#)



Zoom

Sized for Print

EVAPORATOR REMOVAL AND INSTALLATION

REMOVAL SERVICE POINT

SUCTION PIPE OR HOSE, DISCHARGE PIPE DISCONNECTION

CAUTION: Seal the hoses completely, otherwise the compressor oil and receiver will absorb water vapor easily, possibly damaging the condenser and deteriorating performance.

Plug the disconnected hose and the evaporator nipple to prevent foreign material from getting into them.

INSTALLATION SERVICE POINT

>A< EVAPORATOR INSTALLATION

When replacing the evaporator, refill it with the specified amount of compressor oil and install it (to the vehicle).

Compressor oil: SUN PAG56
Quantity: 50 cu.cm (17 fl. oz.)

© 2010 ALLDATA LLC. All rights reserved.
[Terms of Use](#)